

	Type	Hits	Search Text	DBs	Time Stamp
1	IS&R	1080	(219/124.34).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 08:55
2	IS&R	640	(219/125.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 08:50
3	IS&R	472	(901/42).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 08:50
4	IS&R	1263 22	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 08:55
5	IS&R	8360	("901").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 08:55
6	BRS	1342 61	S4 or S5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 08:55
7	BRS	15	S6 and (weld\$3 near10 (torch or robot)) near100 (switch\$3 or contact\$3) near100 (hose or cable) near200 (channel\$1 or orifice\$1 or tube\$1 or pipe\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 09:01

	Type	Hits	Search Text	DBs	Time Stamp
8	BRS	27	(weld\$3 near10 (torch or robot)) near100 (switch\$3 or contact\$3) near100 (hose or cable) near200 (channel\$1 or orifice\$1 or tube\$1 or pipe\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 09:02
9	BRS	9	(weld\$3 near10 (torch or robot)) near100 (switch\$3 or contact\$3) near100 (hose or cable) near200 ((channel\$1 or orifice\$1 or tube\$1 or pipe\$1) near20 (cool\$3 or water or air or gas))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 09:03
10	BRS	85	(weld\$3 near10 (torch or robot)) near100 (hose or cable) near200 ((channel\$1 or orifice\$1 or tube\$1 or pipe\$1) near20 (cool\$3 or water or air or gas))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2007/04/30 09:04